



Standard Wire & Cable Co.

MIL-W-16878 Rev. F Supersession of Duplicate Strandings to MIL-DTL-22759

Former MIL-W-16878 P/N	Description	Replacement MIL-DTL-22759 P/N
MIL-W-16878/4-BCB	E28-7 Silver	MIL-DTL-22759/11-28
MIL-W-16878/4-BDE	E26-19 Silver	MIL-DTL-22759/11-26
MIL-W-16878/4-BEE	E24-19 Silver	MIL-DTL-22759/11-24
MIL-W-16878/4-BFE	E22-19 Silver	MIL-DTL-22759/11-22
MIL-W-16878/4-BGE	E20-19 Silver	MIL-DTL-22759/11-20
MIL-W-16878/4-BHE	E18-19 Silver	MIL-DTL-22759/11-18
MIL-W-16878/4-BJE	E16-19 Silver	MIL-DTL-22759/11-16
MIL-W-16878/4-BKE	E14-19 Silver	MIL-DTL-22759/11-14
MIL-W-16878/4-BLE	E12-19 Silver	MIL-DTL-22759/11-12
MIL-W-16878/4-BMG	E10-37 Silver	MIL-DTL-22759/11-10
MIL-W-16878/4-DCB	E28-7 Silver Alloy	MIL-DTL-22759/22-28
MIL-W-16878/4-DDE	E26-19 Silver Alloy	MIL-DTL-22759/22-26
MIL-W-16878/4-DEE	E24-19 Silver Alloy	MIL-DTL-22759/22-24
MIL-W-16878/4-DFE	E22-19 Silver Alloy	MIL-DTL-22759/22-22
MIL-W-16878/4-DGE	E20-19 Silver Alloy	MIL-DTL-22759/22-20
MIL-W-16878/5-BCB	EE28-7 Silver	MIL-DTL-22759/9-28
MIL-W-16878/5-BDE	EE26-19 Silver	MIL-DTL-22759/9-26
MIL-W-16878/5-BEE	EE24-19 Silver	MIL-DTL-22759/9-24
MIL-W-16878/5-BFE	EE22-19 Silver	MIL-DTL-22759/9-22
MIL-W-16878/5-BGE	EE20-19 Silver	MIL-DTL-22759/9-20
MIL-W-16878/5-BHE	EE18-19 Silver	MIL-DTL-22759/9-18
MIL-W-16878/5-BJE	EE16-19 Silver	MIL-DTL-22759/9-16
MIL-W-16878/5-BKE	EE14-19 Silver	MIL-DTL-22759/9-14
MIL-W-16878/5-BLE	EE12-19 Silver	MIL-DTL-22759/9-12
MIL-W-16878/5-BMG	EE10-37 Silver	MIL-DTL-22759/9-10
MIL-W-16878/5-BNL	EE8-133 Silver	MIL-DTL-22759/9-8
MIL-W-16878/5-DCB	EE28-7 Silver Alloy	MIL-DTL-22759/20-28
MIL-W-16878/5-DDE	EE26-19 Silver Alloy	MIL-DTL-22759/20-26
MIL-W-16878/5-DEE	EE24-19 Silver Alloy	MIL-DTL-22759/20-24
MIL-W-16878/5-DFE	EE22-19 Silver Alloy	MIL-DTL-22759/20-22
MIL-W-16878/5-DGE	EE20-19 Silver Alloy	MIL-DTL-22759/20-20

Former MIL-W-16878 P/N	Description	Replacement MIL-DTL-22759 P/N
MIL-W-16878/25-BCB	E28-7 Nickel	MIL-DTL-22759/12-28
MIL-W-16878/25-BDE	E26-19 Nickel	MIL-DTL-22759/12-26
MIL-W-16878/25-BEE	E24-19 Nickel	MIL-DTL-22759/12-24
MIL-W-16878/25-BFE	E22-19 Nickel	MIL-DTL-22759/12-22
MIL-W-16878/25-BGE	E20-19 Nickel	MIL-DTL-22759/12-20
MIL-W-16878/25-BHE	E18-19 Nickel	MIL-DTL-22759/12-18
MIL-W-16878/25-BJE	E16-19 Nickel	MIL-DTL-22759/12-16
MIL-W-16878/25-BKE	E14-19 Nickel	MIL-DTL-22759/12-14
MIL-W-16878/25-BLE	E12-19 Nickel	MIL-DTL-22759/12-12
MIL-W-16878/25-BMG	E10-37 Nickel	MIL-DTL-22759/12-10
MIL-W-16878/25-DCB	E28-7 Nickel Alloy	MIL-DTL-22759/23-28
MIL-W-16878/25-DDE	E26-19 Nickel Alloy	MIL-DTL-22759/23-26
MIL-W-16878/25-DEE	E24-19 Nickel Alloy	MIL-DTL-22759/23-24
MIL-W-16878/25-DFE	E22-19 Nickel Alloy	MIL-DTL-22759/23-22
MIL-W-16878/25-DGE	E20-19 Nickel Alloy	MIL-DTL-22759/23-20
MIL-W-16878/27-BCB	EE28-7 Nickel	MIL-DTL-22759/10-28
MIL-W-16878/27-BDE	EE26-19 Nickel	MIL-DTL-22759/10-26
MIL-W-16878/27-BEE	EE24-19 Nickel	MIL-DTL-22759/10-24
MIL-W-16878/27-BFE	EE22-19 Nickel	MIL-DTL-22759/10-22
MIL-W-16878/27-BGE	EE20-19 Nickel	MIL-DTL-22759/10-20
MIL-W-16878/27-BHE	EE18-19 Nickel	MIL-DTL-22759/10-18
MIL-W-16878/27-BJE	EE16-19 Nickel	MIL-DTL-22759/10-16
MIL-W-16878/27-BKE	EE14-19 Nickel	MIL-DTL-22759/10-14
MIL-W-16878/27-BLE	EE12-19 Nickel	MIL-DTL-22759/10-12
MIL-W-16878/27-BMG	EE10-37 Nickel	MIL-DTL-22759/10-10
MIL-W-16878/27-BNL	EE8-133 Nickel	MIL-DTL-22759/10-8
MIL-W-16878/27-DCB	EE28-7 Nickel Alloy	MIL-DTL-22759/21-28
MIL-W-16878/27-DDE	EE26-19 Nickel Alloy	MIL-DTL-22759/21-26
MIL-W-16878/27-DEE	EE24-19 Nickel Alloy	MIL-DTL-22759/21-24
MIL-W-16878/27-DFE	EE22-19 Nickel Alloy	MIL-DTL-22759/21-22
MIL-W-16878/27-DGE	EE20-19 Nickel Alloy	MIL-DTL-22759/21-20

Rancho Dominguez

2050 E. Vista Bella Way, Rancho Dominguez, CA 90220
 (310) 609-1811 ● (800) 326-0006 ● FAX: (310) 609-1862
 E-Mail: salesrd@std-wire.com

Phoenix

3120 West Thomas Road, Bldg. #801, Phoenix, AZ 85017
 (602) 269-2501 ● (800) 325-6478 ● FAX: (602) 278-7134
 E-Mail: salesphx@std-wire.com